

10/759575

Attorney Docket No. A-70345-1/DJB/VEJ/RBE
467127-00023
Patent No. 6,877,536



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of:

Max W. DURNEY

Patent No. 6,877,536 *B2*

Issued: April 12, 2005

For: **JOINERY MEMBER AND
FASTENER AND PROCESS AND
APPARATUS FOR PLACEMENT
OF THE FASTENER**

Art Unit: **3725**

Examiner: **Shelley M. Self**

Docket No.: **A-70345-1/DJB/VEJ/RBE**

Certificate of Mail (37 C.F.R. § 1.8(a))

I hereby certify that this paper (along with any referred to as being attached or enclosed) is being deposited with the United States Postal service on the date shown below with sufficient postage as first class mail in an envelope addressed to, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on April 10, 2006.

Patricia A. Diehl

Patricia A. Diehl

Attention Certificate of Corrections Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
APR 17 2006
of Correction

**REQUEST FOR CERTIFICATE OF CORRECTION
UNDER 37 C.F.R. § 1.322**

Sir:

It is hereby requested that a Certificate of Correction be issued for the above-captioned United States Patent. This Certificate of Correction is being requested due to mistakes which appear in the printed patent.

At least one of these typographical mistakes was incurred by fault of the U.S. Patent and Trademark Office, which mistakes are clearly disclosed in the records of the Office (*see e.g.*, AMENDMENT AFTER FINAL, claim 1, line 7). Accordingly, no fee is required with regard to this request.

PATENT

Attorney Docket No. A-70345-1/DJB/VEJ/RBE
467127-00023
Patent No. 6,877,536

Specifically, the printed patent contains the following errors for which a Certificate of Correction is respectfully requested.

In claim 1, col. 13, line 1, "bore to, said shank" should read --bore, said shank--.

In claim 1, col. 13, line 3, "said bore us a result" should read --said bore as a result--.

The above-noted corrections do not involve such changes in the patent as would constitute new matter or would require reexamination.

A completed Form PTO-1050 accompanies this request, with the above-noted corrections printed thereon. Accordingly, a Certificate of Correction is believed proper and issuance thereof is respectfully requested.

The Commissioner is hereby authorized to charge any fee deficiency, or credit any overpayment, to our Deposit Account No. 50-2319 (Order No. 467127-00023; Docket No. A-70345-1/DJB/VEJ/RBE).

Prompt and favorable consideration of this Request for Certificate of Correction is respectfully requested.

Respectfully submitted,

By:


Victor E. Johnson, Reg. No. 41,546

Date: April 10, 2006

DORSEY & WHITNEY LLP
555 California Street, Suite 1000
San Francisco, California 94104-1513
Telephone: (415) 781-1989 Facsimile: (415) 398-3249

REQUEST FOR CERTIFICATE OF
CORRECTION
4814-0962-1760\1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,877,536 *B2*

DATED : April, 12, 2005

INVENTOR(S) : Max W. DURNEY

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In claim 1, col. 13, line 1, replace "bore to, said shank" with --bore, said shank--.

In claim 1, col. 13, line 3, replace "said bore us a result" with --said bore as a result--.

MAILING ADDRESS OF SENDER:

DORSEY & WHITNEY LLP
Suite 1000
555 California Street
San Francisco, California 94104
Telephone: (415) 781-1989
Fax: (415) 398-3249

PATENT NO. 6,877,536
No. of additional copies
>> 0